Edgar Filing: ENTERGY ARKANSAS INC - Form 8-K

ENTERGY ARKANSAS INC Form 8-K May 20, 2013

Commission Registrant, State of

File Number Incorporation, Address of

Principal Executive Offices,

SECURITIES AND EXCHANGE COMMISSION

Washington, D.C. 20549

FORM 8-K CURRENT REPORT

Pursuant to Section 13 or 15(d) of the Securities Exchange Act of 1934

Date of Report (Date earliest event reported) May 20, 2013

Commission Registrant, State of

File Number Incorporation, Address of

Principal Executive Offices,

	Telephone Number, and IRS Employer Identification No	o. 1-10764	Telephone Number, and IRS Employer Identification No. ENTERGY ARKANSAS, INC.
1-112	ENTERGY CORPORATION (a Delaware corporation) 639 Loyola Avenue New Orleans, Louisiana 70113 Telephone (504) 576-4000 72-1229752	1-10/04	(an Arkansas corporation) 425 West Capitol Avenue Little Rock, Arkansas 72201 Telephone (501) 377-4000 71-0005900
	k the appropriate box below if the Form gistrant under any of the following provi	_	intended to simultaneously satisfy the filing obligation of eneral Instruction A.2.):
[]	Written communications pursuant to Rule 425 under the Securities Act (17 CFR 230.425)		
[]	Soliciting material pursuant to Rule 14a-12 under the Exchange Act (17 CFR 240.14a-12)		
[]	Pre-commencement communications pursuant to Rule 14d-2(b) under the Exchange Act (17 CFR 240.14d-2(b))		
[]	Pre-commencement communications pu	ırsuant to Rul	e 13e-4(c) under the Exchange Act (17 CFR 240.13e-4(c))
Item 8.01 Other Events.			
ANO Damage and Outage.			

Edgar Filing: ENTERGY ARKANSAS INC - Form 8-K

On March 31, 2013, during a scheduled refueling outage at ANO 1, a contractor-owned and operated heavy-lifting apparatus collapsed while moving the generator stator out of the turbine building. The collapse resulted in the death of an ironworker and injuries to several other contract workers, caused ANO 2 to shut down, and damaged the ANO turbine building. The turbine building serves both ANO 1 and 2 and is a non-radiological area of the plant. Entergy is still analyzing the incident and the extent of the damage. The total cost of assessment, debris removal, and replacing damaged property and equipment is currently estimated to be in the range of \$130 million to \$215 million. This estimate may change as restoration efforts continue and more detailed analysis is performed. Entergy Arkansas restarted ANO 2 on April 28, 2013 and the unit reached full power on April 30, 2013. Restoration and restart efforts with respect to ANO 1 are ongoing and are expected to be complete before the end of 2013. In addition, Entergy Arkansas incurred replacement power costs for ANO 2 power during its outage and expects to incur incremental replacement power costs for ANO 1 power to the extent its outage extends beyond the originally-planned duration of the refueling outage. Each of the Utility operating companies has recovery mechanisms in place designed to recover its prudently-incurred fuel and purchased power costs.

Entergy Arkansas is assessing its options for recovering damages that resulted from the stator drop, including its insurance coverage. Entergy is a member of Nuclear Electric Insurance Limited (NEIL), a mutual insurance company that provides property damage coverage to the members' nuclear generating plants, including ANO. NEIL has notified Entergy that it believes that a \$50 million course of construction sublimit applies to any loss associated with the lifting apparatus failure and stator drop at ANO. Entergy has responded that it disagrees with NEIL's position and is evaluating its options for enforcing its rights under the policy.

SIGNATURE

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has duly caused this report to be signed on its behalf by the undersigned hereunto duly authorized.

Entergy Corporation Entergy Arkansas, Inc.

By: /s/Alyson M. Mount Alyson M. Mount Senior Vice President and Chief Accounting Officer

Dated: May 20, 2013